

Plug & Drive Studio changelog

Contents

- 1 Release 1.1.0.....3**
 - 1.1 Changes.....3
- 2 Release 1.0.4.....3**
- 3 Release 1.0.3.....3**
- 4 Release 1.0.2.....3**
 - 4.1 Changes.....3
- 5 Release 1.0.1.....3**
 - 5.1 Changes.....3
- 6 Release 1.0.....3**
 - 6.1 Fieldbus related changes..... 3
 - 6.2 Other Changes..... 3

1 Release 1.1.0

1.1 Changes

1. Added support for HMS IXXAT driver VCI 4.0 (CANopen).
2. Additional folder for `od.xml` files. Insert an `od.xml` into the path `%PNDS_INSTALL_FOLDER%\workspace\od-metadata`, PnD Studio will recognize and use this file in the connection wizard as well. Therefore it is not longer necessary to load this `od.xml` in the connection wizard manually.

2 Release 1.0.4

Fixed bug not correctly showing MODBUS VCP controller in connection setup.

3 Release 1.0.3

Fixed bug related to local language settings, added warning in case the firmware is newer than FIR-v1650.

4 Release 1.0.2

4.1 Changes

Fixed bug in importing OD table and stabilized NanoJ upload.

5 Release 1.0.1

5.1 Changes

Changed recommended firmware version to FIR-v1650-B527540

6 Release 1.0

6.1 Fieldbus related changes

- Full support of all N5 with REST
- Support of Modbus/TCP
- Support of EtherCAT
- Support of Peak adapter for CANopen

6.2 Other Changes

- Multiple number of CANopen IXXAT Adapters are now supported
- The OD table filters are now stored